

Menu

HISTORY FILE MAP for year 2003


REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

098.22:31-22:35 12m 1024bps realtime data lost during additional 1-way to 2-way
098.22:58-23:06 transistions after the transmitter tripped off at DSS-24.
DR G102620 refers.



100.01:01-01:13 12m 1024bps realtime data lost during long 2-way to 1-way
transition at DSS-24. No DR raised.